

REVIEW PART 2

Replacement Engine Installation

Insert the word (letter option) that better fits. Wrong answers will be penalized with - (9 marks)

Air Transat _____ (1) an engine change on the accident airplane _____ (2) metal chips found on the original engine's master chip detector during a routine inspection. Air Transat's spare engine was not available for the replacement, _____ (3) the airline used a Rolls-Royce loaned engine that _____ (4) at the Air Transat facility. All of Air Transat's A330 airplanes _____ (5) in a post-mod configuration. The loaned replacement engine was a pre-mod hydraulic pump configuration. The maintenance facility that prepared the loaned engine for installation on an airplane was supposed _____ (6) the engine build-up service bulletin so the newer modified hydraulic pumps could be used. However, the shop _____ (7) the bulletin because required parts were not available. _____ (8) the required service bulletin had not been incorporated, the engine _____ (9) to Air Transat with a Carry Forward List specifying that the new modified hydraulic pump numbers were to be installed.

- 1.
- 2.
- 3.
- 4.
- 5.



Vista previa del documento.

Mostrando 2 páginas de 4

6. a. to incorporate c. that they incorporate
b. incorporating d. incorporate
7. a. have not completed c. did not complete
b. do not complete d. will not complete
8. a. However b. Since c. Therefore d. Even though
9. a. had been transported c. was transported
b. have been transported d. will be transported

1 – 9

c c c b d a c d c



WUOLAH

Vista previa del documento.

Mostrando 2 páginas de 4